

Oil Field Environmental Incident Summary

Incident: MFB00000057

Date/Time of Notice: 01/05/2006 09:20

Responsible Party:

Well Operator: ZENERGY, INC

Well Name: JACKSON 1-29H

Field Name: FOREMAN BUTTE

Well File #: 15666

Date Incident: 1/4/2006

Time Incident: 11:30

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 102

Sec: 28

Qtr: SW SW

Location Description: Leak occurred in the NENE Section 33-150-102 approximately 150 to 200 yards west of County Rd 15 on south side of lease road.

Submitted By: Robert Graham

Received By: Mark Bohrer

Contact Person: Robert Graham
6100 S YALE AVE
SUITE 1700
TULSA, OK 74136

General Land Use: Pasture

Affected Medium: Soil and Water

Distance Nearest Occupied Building: 0.5 Miles

Distance Nearest Water Well: 0.5 Miles

Type of Incident Pipeline Leak

Release Contained in Dike No

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels	0	barrels
Brine	4500	barrels	2080	barrels	0	barrels
Other	0	barrels	0	barrels	0	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/5/2006

Clean Up Concluded:

Risk Evaluation:

Contaminated surface water.

Areal Extent:

See below.

Potential Environmental Impacts:

Soil and water contamination.

Action Taken or Planned:

Isolated leak, dug up and repaired line. Pressure tested line and put back in service. Vac trucks have recovered 1120 barrels out of stock dam and 960 barrels from collection point below stock dam. Plan to remove all water from stock dam and any other standing water in drainage. Will take water samples. They have meters on all transfer pumps and I suggested they install meter in line at disposal well to monitor line. Informed Robert that soil excavation may be required. Requested a remediation plan be submitted and informed him that I would contact Health Department and have them call him.

Wastes Disposal Location: Put into reserve pits to settle out solids and then haul to Wolf SWD #1.

Agencies Involved: